


GB745
PARTS LIST



WARNING:
This tool incorporates a patented hydraulic valve. When overhauling tool, o-ring (A-287), back-up ring (401101), retaining ring (400936) and spring (50806) must be replaced. Failure to do so could result in SEVERE PERSONAL INJURY!

